



# Product Bulletin

GEOSPATIAL DIVISION

8 JULY 2020

**TRIMBLE DISTRIBUTOR CONFIDENTIAL**

## TRIMBLE R10 FAMILY BATTERY SUPPLY CONSTRAINTS

### Temporary reduction in number of batteries included with Trimble R10 family GNSS systems

As part of the response to the COVID-19 pandemic, battery production capacity worldwide has been reprioritized toward devices used in medical applications. This has resulted in non-medical device manufacturers experiencing longer-than-usual lead times for common battery components. Consequently, Trimble is faced with a temporary shortage of our main system battery for the R10 family of GNSS receivers, P/N 76767.

To address the shortage, Trimble is taking the necessary step of temporarily reducing the quantity of batteries included with Trimble R10 family GNSS systems from 2 to 1. This measure, which will allow us to maintain product availability until supply chain constraints have lifted, is in effect as of 8 July 2020.

Trimble will continue to monitor the global supply chain situation and will revisit this change as soon as is feasible.

We appreciate your understanding in these circumstances.

#### Affected products

Description of affected products	Change to Bill of Materials effective 8 July 2020
ALL Trimble R10 family GNSS system packouts (includes Trimble R10, Trimble R10 Model 2, and Trimble R12 GNSS systems)	P/N 76767 quantity reduced from 2 to 1

#### For more information

For more information, contact your local Trimble sales representative.

<http://surveypartners.trimble.com>

© 2020, Trimble Inc. All rights reserved. Trimble, the Globe & Triangle logo, CenterPoint, and xFill are trademarks of Trimble Inc., registered in the United States and in other countries. Access, ProPoint, SurePoint, and TerraFlex are trademarks of Trimble Inc. All other trademarks are the property of their respective owners.